


Figure 3: Historic Photograph

Name of Property: Dr. A.G. Schnack House
City or Vicinity: Honolulu
Photographer: Unknown
Date Photographed: c. 1918
Description of Photograph: Aerial view of Dowsett Avenue in Nuuanu Valley, taken from Pacific Heights



Source: Hawaii State Archives Department

Figure 4: Elevations




Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka

ELEVATIONS


[illegible]

FOUNDATION PLAN

Figure 6: First Floor Plan




Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka




FIRST FLOOR PLAN

Figure 7: Second Floor Plan




Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka



SECOND FLOOR PLAN

Figure 8: Details




DETAILS

Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka

FLOWER BOX DETAILS




Figure 10: Section Cut and Details



Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka

SECTIONS AND DETAILS

Figure 11: Detail of Fireplaces for Living Room and Sun Room




Drawing credit: Dowsett Tract, Mar 1927
Signed by S. Uyeoka

DETAIL OF FIREPLACES

Figure 12: Historic Photograph

Name of Property: Dr. A.G. Schnack House
City or Vicinity: Honolulu
Photographer: Unknown
Date Photographed: unknown
Description of Photograph: view of front yard and koi pond



Source: Found in AG Schnack Residence

Figure 13: Historic Photograph

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Unknown

Date Photographed: unknown

Description of Photograph: view of porte-cochere



Source: Found in AG Schnack Residence

Figure 14: Historic Photograph

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Unknown

Date Photographed: unknown

Description of Photograph: view of arched front entry



Source: Found in AG Schnack residence

Photographs:

Photo #	Name	Description
1 of 10	Setting	View from Alika Ave. driveway, camera facing south
2 of 10	Property Exterior	View of Front Door Entry through porte cochere
3 of 10	Setting	View of front yard looking towards Alika Ave.
4 of 10	Property Exterior	View of garage, camera facing west
5 of 10	Property Exterior	View of rear elevation, camera facing west
6 of 10	Property Exterior	Rear entry on rear elevation accessing Sun Room
7 of 10	Property Exterior	Side elevation, camera facing southwest
8 of 10	Property Interior	Interior view of Living Room
9 of 10	Property Interior	Interior view of railing
10 of 10	Property Interior	Interior view of stairs from second floor

**Photo Key:
Setting and Property Photos**

