

Photo 1 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: View from Alikā Ave. driveway, camera facing south



Photo 2 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: View of Front Door Entry through porte cochere



Photo 3 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: View of front yard looking towards Alika Ave.



Photo 4 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: View of garage, camera facing west



Photo 5 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: View of rear elevation, camera facing west



Photo 6 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: Rear entry on rear elevation accessing Sun Room



Photo 7 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: Side elevation, camera facing southwest



Photo 8 of 10:

Name of Property: Dr. A.G. Schnack House
City or Vicinity: Honolulu
Photographer: Natalie Besl
Date Photographed: March 2017
Description of Photograph: Interior view of Living Room



Photo 9 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: Interior view of railing



Photo 10 of 10:

Name of Property: Dr. A.G. Schnack House

City or Vicinity: Honolulu

Photographer: Natalie Besl

Date Photographed: March 2017

Description of Photograph: Interior view of stairs from second floor

